

<b>Last Modified:</b> 12-04-2024	6.11:8.1.0	<b>Doc ID:</b> RM100000029ZW8
<b>Model Year Start:</b> 2023	<b>Model:</b> Prius Prime	<b>Prod Date Range:</b> [12/2022 - ]
<b>Title:</b> HEATING / AIR CONDITIONING: AMBIENT TEMPERATURE SENSOR: REMOVAL; 2023 - 2024 MY Prius Prius Prime [12/2022 - ]		

## REMOVAL

### CAUTION / NOTICE / HINT

The necessary procedures (adjustment, calibration, initialization or registration) that must be performed after parts are removed and installed, or replaced during thermistor assembly and lever set removal/installation are shown below.


#### Necessary Procedures After Parts Removed/Installed/Replaced




REPLACED PART OR PERFORMED PROCEDURE	NECESSARY PROCEDURES	EFFECT/INOPERATIVE FUNCTION WHEN NECESSARY PROCEDURES ARE NOT PERFORMED	LINK
Front bumper assembly*	Front television camera view adjustment	Panoramic View Monitor System	<a href="#">INFO</a>
		Advanced Park	<a href="#">INFO</a>

\*: Even when not replacing the part, it is necessary to perform the specified necessary procedures after installation.


### CAUTION / NOTICE / HINT




#### COMPONENTS (REMOVAL)



	PROCEDURE	PART NAME CODE			
1	RADIATOR SUPPORT OPENING COVER	53289A	-	-	-
2	THERMISTOR ASSEMBLY	88790B	-	-	-

*A	w/o Grille Shutter	*B	for M20A-FXS
*C	for 2ZR-FXE	-	-



	PROCEDURE	PART NAME CODE			
3	FRONT BUMPER ASSEMBLY	-	-	-	-
4	FRONT RADIATOR SIDE AIR GUIDE PLATE LH	16695A	-	-	-
5	THERMISTOR ASSEMBLY	88790B	-	-	-


*A	w/ Grille Shutter	-	-
----	-------------------	---	---

## PROCEDURE

### 1. REMOVE RADIATOR SUPPORT OPENING COVER (w/o Grille Shutter)

Click here [INFO](#)

### 2. REMOVE THERMISTOR ASSEMBLY (w/o Grille Shutter)



**3. REMOVE FRONT BUMPER ASSEMBLY (w/ Grille Shutter)**

Click here [INFO](#)

**4. REMOVE FRONT RADIATOR SIDE AIR GUIDE PLATE LH (w/ Grille Shutter)**

Click here [INFO](#)

**5. REMOVE THERMISTOR ASSEMBLY (w/ Grille Shutter)**

